

ShaMaran Petroleum Corp. Reports Incident at Sarsang Facility

15.07.2025 | [CNW](#)

[ShaMaran Petroleum Corp.](#) ("ShaMaran" or the "Company") (TSXV: SNM) (Nasdaq First North: SNM) has been informed by HKN Energy Ltd. ("HKN"), the operator of the Sarsang Block in the Kurdistan Region of Iraq, that an explosion occurred earlier today at approximately 7:00 AM local time at one of the production facilities in the Sarang field.

All personnel have been safely accounted for, and no injuries have been reported. HKN has initiated a full assessment of the situation and is coordinating closely with local authorities and relevant stakeholders to manage the response and ensure the safety of surrounding communities.

Operations at the field have been suspended until the site is secure and a full evaluation is completed.

ShaMaran and HKN are committed to the highest standards of safety and environmental responsibility and will provide further updates as more information becomes available.

About ShaMaran Petroleum Corp.

ShaMaran is a Canadian independent oil and gas company focused on the Kurdistan region of Iraq. The Company indirectly holds a 50% working interest in the Atrush Block and an 18% working interest in the Sarsang Block. The Company is listed in Toronto on the TSX Venture Exchange and in Stockholm on Nasdaq First North Growth Market (ticker "SNM"). ShaMaran is part of the Lundin Group of Companies.

Important Information

ShaMaran is obliged to make this information public pursuant to the EU Market Abuse Regulation. This information was submitted for publication through the agency of the contact person set out below on July 15, 2025, at 2:30 a.m. Eastern Time.

The Company's certified advisor on Nasdaq First North Growth Market is FNCA Sweden AB.

Neither TSX Venture Exchange nor its Regulation Services Provider (as that term is defined in the policies of the TSX Venture Exchange) accepts responsibility for the adequacy or accuracy of this release.

SOURCE ShaMaran Petroleum Corp.

Contact

Elvis Pellumbi, CFO, +41 22 560 8600, info@shamaranpetroleum.com, www.shamaranpetroleum.com

Dieser Artikel stammt von [Rohstoff-Welt.de](#)

Die URL für diesen Artikel lautet:

<https://www.rohstoff-welt.de/news/698595--ShaMaran-Petroleum-Corp.-Reports-Incident-at-Sarsang-Facility.html>

Für den Inhalt des Beitrages ist allein der Autor verantwortlich bzw. die aufgeführte Quelle. Bild- oder Filmrechte liegen beim Autor/Quelle bzw. bei der vom ihm benannten Quelle. Bei Übersetzungen können Fehler nicht ausgeschlossen werden. Der vertretene Standpunkt eines Autors spiegelt generell nicht die Meinung des Webseiten-Betreibers wieder. Mittels der Veröffentlichung will dieser lediglich ein pluralistisches Meinungsbild darstellen. Direkte oder indirekte Aussagen in einem Beitrag stellen keinerlei Aufforderung zum Kauf-/Verkauf von Wertpapieren dar. Wir wehren uns gegen jede Form von Hass, Diskriminierung und Verletzung der Menschenwürde. Beachten Sie bitte auch unsere [AGB/Disclaimer!](#)

Die Reproduktion, Modifikation oder Verwendung der Inhalte ganz oder teilweise ohne schriftliche Genehmigung ist untersagt!
Alle Angaben ohne Gewähr! Copyright © by Rohstoff-Welt.de -1999-2026. Es gelten unsere [AGB](#) und [Datenschutzrichtlinien](#).